

Replacement Fan Clutch Repair Kits for KYSOR® K26RA, K30RA and K32RA

Benefit from Horton's industry-leading customer service and quality, even if you are running its competitors' fan drives in your fleet.

- **Dual pilot for reduced inventory and complete application coverage**
- **Two-piece liner design for quick repairs**
- **Superior liner material for longer life and reliability**

Count on Horton to not only provide the reliable, durable products you need, but to deliver them on time



ENGINEERED FOR:





Rear-Air Fan Clutch

Horton # 9908504

Replaces

1090-09650-01
1090-09750-01
8801X
8801N
8905N
8901N
9908501
9908503



Hub Bearing Kits

Horton # 9908300

Replaces

1033-07781-01
8581-01

Horton # 9908301

Replaces

1033-07782-01
8582-01

Horton # 9908302

Replaces

1033-07782-02
8582-02

Horton # 9908303

Replaces

1033-07782-03
8582-03

Horton # 9908304

Replaces

1033-07782-04
8582-04



Rear-Air Major Kit

Horton # 9908408

Replaces

1033-40600-02
8800SKL



Rear-Air Seal Kit

Horton # 9908409

Replaces

1033-08233-01
8500SK



Lining Kit

(fit's both rear-air and front-air fan clutches)

Horton # 9908407

Replaces

1033-40600-01
8800L

Visit catalog.hortonww.com

to view full list of part number cross references!

Committed to Your Ideal Airflow Solution

Horton® is the premium provider of engine cooling solutions worldwide. Our culture of innovation delivers high-performance products that last and services that help you meet your commitments. Trust Horton to help your products last longer, run quieter and consume less fuel.

Horton is IATF 16949, ISO 14001 and ISO 9001 certified.